



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
June 9

Repair Work

Devil's Slide (post mile 39.14)

- Whaler wall construction above and below the road:
Whaler wall 'A' below the road – foundation excavation, rebar installation and concrete work taking place simultaneously on different sections.

Whaler wall 'D' above the road – installing formed rebar and concrete work continues on different sections.
- Drilling and tie back installation:
'Condon & Johnston' continued tie back work on wall 'A' below the road. 25 out of 59 now complete. Tie back stressing began to-day.

'Drill Tech' continued drilling for tie backs at wall 'C'. 8 out of 34 now complete.

Signs

- Two more advisory signs were installed to-day at the following locations:
Westbound 92 at Ralston Avenue
Northbound 280 before Highway 92
Both signs read '1 Closed at Devil's Slide'; 'MONTARA HALF MOON BAY BUSINESSES OPEN'.